

Code: LG-058

Name: LG Washing Machine Door Interlock

Compatible with:

LG F1255FDS7, F1255RDS27, F12U2QNP7S, F12U2QNP7S, F1495BDSK6,
F14U1JBBS2, F14U1JBBS2, F14U2TDN0, F14U2TDN0, F2J5HNP7T, F2J5HNP7T,
F2J5NNP7S, F2J5NNP7S, F2J5QNP7S, F2J5TNP3W, F2J5TNP3W, F2J5TNP3W,
F2J5TNP3W, F2J5TNP7S, F2J5TNP7S, F2J5TNP7S, F2J5TNP7S, F2J5TNP7S,
F4J5QNP7S, F4J5QNP7S, F4J5QNP7S, F4J5VYP7SP, F4J6TMP8S, F4J6TMP8S,
F4J6TMP8S, F4J6TMP8S, F4J6TNP0W, F4J6TNP0W, F4J6TNP8S, F4J6TNP8S,
F4J6TNP8S, F4J6VYP2S, F4J6VYP2S, F4J6VYP2S, F4J6VYP2W, F4J6VYP2W,
F4J6VYP2W, F4J7JYP2T, F4J7THP2S, F4J7TNP8S, F4J7VNP8S, F4J7VNP8S,
F4J7VYP8S, F4J7VYP8S, F4J8FH2S, F4J8JH2W, F4J9JHP2T, F4J9JHP2T,
F4V5RGP2T, F4V5RYP2T, F4V5RYP2T, F4V5VGP2T, F4V5VYP2T, F4V7VCP2T,
F4V7VWP2T, F4V9RCP2E, F4V9RCP2E, F4V9RWP2E, F52590WH, F52590WH,
F52592WH, F52592WH, F52596IXS, F52596IXS, FH069FD3FS, FH069FD3PS,
FH0C9CDHK72, FH0D7DDMK02, FH0D7DDMK02, FH0D7DDMK02,
FH4U1FCHK4N, FH4U1JBHK4N, FH4U1JBSK4, FH4U2FHP2S, FH4U2JHP2D,
FH4U2JHP2T, FH4U2TDHP5N, FH4U2TGP2S, FH4U2TGP2S, FH4U2TMP8S,
FH4U2TNP8S, FH4U2TNP8S, FH4U2TYP2S, FH4U2TYP2S, FH4U2VDNP5,
FH4U2VYP2C, FH4U2VYP2C, FH4U2VYP2S, FH6G1BCHK6N, FH6G1BCHK6N,
WD991276RCS